



NEW MEXICO ENERGY, MINERALS
and
NATURAL RESOURCES
DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178
FAX: (505) 334-6170
www.emnrd.state.nm.us/ocd/District 3/district3.htm

BRADENHEAD TEST REPORT

(Submit 2 copies to above address)

Date of Test 9-1-05 Operator Robert L. Bayless API #30-0
Producer LLC 45-09630

Property Name Helen Hartman-DAK MV Well No. 1 Location: Unit P Section 8 Township 30N Range 11W

Well Status (Shut-In or Producing) Tubing 200 Intermediate Casing 230 Bradenhead 3PSI

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

TIME	PRESSURES:			BRADENHEAD FLOWED	INTERMEDIATE FLOWED
	BRADENHEAD	INTERMEDIATE	CASING		
5 minutes	0		230	Steady Flow	
10 minutes	0		230	Surges	
15 minutes	0		230	Down to Nothing X	
20 minutes	0		230	Nothing	
25 minutes	0		230	Gas	
30 minutes	0		230	Gas & Water	
				Water	


If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN BRADENHEAD 0 INTERMEDIATE

REMARKS:

Blew down to OPSI



By Bradley Aranda

Witness

Perfer
(Position)