



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410

(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 3-29-13 Operator Chewron API #30-0 39-24876

Property Name Lincoln Well No. 301 Location: Unit 25 Township 27 Range 7

Well Status (Shut-In or Producing) Producing Initial PSI: Tubing 21.2 Intermediate N/A Casing 20.0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>20</u>		
10 min	<u>0</u>		<u>20</u>		
15 min	<u>0</u>		<u>20</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>DIST. 3</u>
Nothing	<u>OIL CONS. DIV.</u>
Gas	
Gas & Water	<u>PROD MAR 20 13</u>
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

Blow down in 2 seconds

By Randy Catcott
caldersource
(Position)

Witness Mona Kuhlberg

E-mail address Randy Catcott Randy.C@caldersource.com