



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://amnd.state.nm.us/ocd/District11123District.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

OIL CONS. DIV DIST. 3

MAR 22 2013

Date of Test 3-18-13 Operator Chenon incident API #30-039-82371

Property Name Rincon Well No. 141 Location: Unit C Section 27 Township 27 Range 6

Well Status (Shut-In or Producing) Initial PSI: Tubing 22 Intermediate X Casing 98 Bradenhead Q

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE			INTERM	
	Bradenhead BH	Int	Csg	Int	Csg
5 min	0	1	98		
10 min	0	1	98		
15 min	0	1	98		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing <u>X</u>	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD Q

INTERMEDIATE X

REMARKS:

By Randy calder
calder services
(Position)

Witness _____

E-mail address Randy.c@calderservices.com

3-20-13