

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☒ Initial Report ☐ Final Report

Name of Company ConocoPhillips Company	Contact Lisa Hunter
Address 3401 East 30th Street, Farmington, NM	Telephone No. 505-326-9786
Facility Name San Juan 28-7 244M	Facility Type Gas Well

Surface Owner BLM	Mineral Owner BLM	API No. 3003926873
--------------------------	--------------------------	---------------------------

LOCATION OF RELEASE

Unit Letter D	Section 7	Township 27N	Range 7W	Feet from the 850'	North/South Line North	Feet from the 965'	East/West Line West	County Rio Arriba
-------------------------	---------------------	------------------------	--------------------	------------------------------	----------------------------------	------------------------------	-------------------------------	-----------------------------

Latitude 36.5932 Longitude -107.62078

NATURE OF RELEASE



Type of Release Produced Water Condensate	Volume of Release Produced Water 36.74 BBLs Condensate 5.01 BBLs	Volume Recovered 0 BBL 0 BBL
Source of Release Production Tank	Date and Hour of Occurrence Unknown	Date and Hour of Discovery 03-06-2013; 9:00 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Brandon Powell - NMOCD Mark Kelly - BLM FFO	RCVD MAR 18 '13 OIL CONS. DIV.
By Whom? Lisa Hunter	Date and Hour NMOCD - 03-06-2013 @ 1:51 PM BLM FFO - 03-06-2013 @ 1:51 PM	DIST. 3
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
Production tank developed a leak due to corrosion causing the release of 36.74 BBLs of Produced Water and 5.01 BBLs of Condensate. Zero BBLs were recovered.

Describe Area Affected and Cleanup Action Taken.*
ConocoPhillips will replace the tank and assess the soils to determine further action, if needed.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Lisa Hunter	Approved by Environmental Specialist: 	
Title: Field Environmental Specialist	Approval Date: 3/26/2013	Expiration Date:
E-mail Address: Lisa.Hunter@cop.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: March 13, 2013 Phone: 505-326-9786		

* Attach Additional Sheets If Necessary

NSK 1308536513