



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6178
<http://amrhd.state.nm.us/ocd/District1112/district.htm>

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

APR 04 2013

Date of Test 3-28-13 Operator Chenvar midcont API #30-0 39-06773

Property Name Birca Well No. 24 Location: Unit M Section 32 Township 27 Range 6

Well Status (Shut-In or Producing) Initial PSI: Tubing 23 Intermediate X Casing 85 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		85		
10 min	0		84		
15 min	0		85		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS		BRADENHEAD	INTERMEDIATE
Steady Flow			
Surges			
Down to Nothing			
Nothing	X		
Gas			
Gas & Water			
Water			

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE X

REMARKS:

By Randy calder
calder services
(Position)

Witness _____

E-mail address Randy.c@calderservices.com

4-2-13