



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

RCVD APR 10 '13
OIL CONS. DIV.
DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 10-APR-2013 Operator Burlington API #30-0 39-23738

Property Name LINDAITHBURY Well No. 34 Location: Unit 6 Section 32 Township 25 Range 2

Well Status(Shut-In or Producing) Initial PSI: Tubing 90.5 Intermediate NA Casing 90.5 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead	Csg	Int	Csg
TIME					
5 min	{	N/A	90.5	X	X
10 min		N/A	90.5		
15 min		N/A	90.5		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	X
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE _____

REMARKS:

OPENED THE BRADEN HEAD AND NOTHING CAME
OUT

By

Burl Dwyer

(Position)

Witness

Sam Dwyer

E-mail address _____