



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III3district.htm](http://emnrd.state.nm.us/ocd/District%20III3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 10-APRIL-2013 Operator BURLINGTON API #30-0 39-24089
Property Name LIVORTH B^{UNIT} Well No. 73 Location: Unit A Section 6 Township 24 Range 2
Well Status(Shut-In or Producing) Initial PSI: Tubing 245 Intermediate N/A Casing 232 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead	Csg	Int	Csg
TIME					
5 min		N/A	232		
10 min		N/A	232		
15 min		N/A	232		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	X
Nothing	
Gas	X
Gas & Water	
Water	

RCVD APR 10 '13
OIL CONS. DIV.
DIST. 3

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD _____ INTERMEDIATE _____

REMARKS:

OPENED THE BRADEN HEAD AND IT BLEW
DOWN TO NOTHING IN LESS THAN 1 SECOND

By

Witness

(Position)

E-mail address _____