



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

RCVD APR 15 '13
OIL CONS. DIV.

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

DIST. 3

Date of Test 15-APR-2013 Operator CONOCO API # 30-039 30450

Property Name SAN JUAN 27-4 well Well No. 22M Location: Unit Section H Township 27 Range 4

Well Status (Shut-In or Producing) Initial PSI: Tubing 184 Intermediate 0 Casing 181 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	<u>5</u>	<u>0</u>	<u>184</u>	<u>5</u>	<u>184</u>
10 min	<u>5</u>	<u>0</u>	<u>184</u>	<u>5</u>	<u>184</u>
15 min	<u>5</u>	<u>0</u>	<u>184</u>	<u>5</u>	<u>184</u>
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>X</u>
Nothing	<u>X</u>
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS:

OPENED THE BRADEN HEAD NOTHING CAME OUT.
OPENED THE INTERMEDIATE AND IT BLEW DOWN TO NOTHING
IN 11 SECONDS.

By MSO
(Position)

Witness 50M20KMS

E-mail address