



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://femnr.state.nm.us/ocd/District III/3district.htm](http://femnr.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

APR 11 2013

BRADENHEAD TEST REPORT
(submit 1 copy to above address)

Date of Test 4-8-13 Operator Chewer midcont API #30-0 39-06994

Property Name Rincon Well No 66 Location: Unit H Section 22 Township 27 Range 7

Well Status (Shut-In or Producing) Initial PSI: Tubing 90 Intermediate X Casing 91 Bradenhead 2

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				INTERM	
	BH	Int	Csg		Int	Csg
TIME	Light Flow		91			
5 min	Light Flow		91			
10 min	Light Flow		91			
15 min	Light Flow		91			
20 min	Light Flow		91			
25 min	Light Flow		91			
30 min	Light Flow		91			

FLOW CHARACTERISTICS		BRADENHEAD		INTERMEDIATE	
Steady Flow	<u>X</u> Light				
Surges					
Down to Nothing					
Nothing					
Gas					
Gas & Water					
Water					

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 1

INTERMEDIATE X

REMARKS:

By Randy Culcote

Witness _____

Culder service
(Position)

E-mail address Randy.C@calderservice.com

4-9-13