



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrnr.state.nm.us/ocd/District III3/district.htm](http://emrnr.state.nm.us/ocd/District%20III3/district.htm)

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

APR 11 2013

Date of Test 4-8-13 Operator C. Mervon midcut API # 30-039-25207

Property Name Rincon Well No 136E Location: Unit D Section 23 Township 27 Range 7

Well Status (Shut-In or Producing) Initial PSI: Tubing 76 Intermediate X Casing 88 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead	Csg	Int	Csg
TIME					
5 min	0		88		
10 min	0		90		
15 min	0		91		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing <u>X</u>	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE X

REMARKS:

By Randy Culcote

Witness _____

Culder service

(Position)

E-mail address Randy.C@calderservice.com

4-9-13