



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

RCVD APR 24 '13
OIL CONS. DIV.
DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4/24/2013 Operator Burlington API #30-0 39-06282
Property Name Hughes Well No. 9 Location: Unit N Section 30 Township 26 Range 7
Well Status (Shut-In or Producing) Initial PSI: Tubing 22 Intermediate NA Casing 22 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE				
	Bradenhead BH	Int	Csg	INTERM Int	Csg
5 min	0.1		26		
10 min	0.1		27		
15 min	0.1		28		
20 min	0.1		28		
25 min	0.1		29		
30 min	0.1		29		

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow	X	
Surges		
Down to Nothing		
Nothing		
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 1.4 INTERMEDIATE NA

REMARKS:

Initial gauge used on BH read 0, did not have subunits, changed gauge after finding pressure flow to note tenths unit pressures, BH had steady flow throughout test, requested gas analysis.

By M. S. C. me

Witness Jonathan D. Kelly

M. S. C.
(Position)

E-mail address _____