

OIL CONSERVATION DIVISION AZTEC DISTRICT OFFICE 1000 RIO BRAZOS ROAD **AZTEC NM 87410** (505) 334-6178 FAX: (505) 334-6170

http://emnrd.state.nm.us/ocd/District III/3distric.htm

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

RCVD APR 24'13 OIL CONS. DIV. DIST. 3

Date of Test 4/24/2013 Operator	Bullington API #30-039-30380
Property Name Lively Well No. 211	Location: Unit M Section 31 Township 27 Range 7
Well Status(Shut-In or Producing) Initial PSI: Tubing 220 Intermediate NA Casing 233 Bradenhead 58	
OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH	
PRESSURE Testing Bradenhead INTERM BH Int Csg Int Csg	FLOW CHARACTERISTICS BRADENHEAD INTERMEDIATE
TIME 0 5 246 \	Steady Flow
10 min 0 257	Surges
15 min 0 251	Down to Nothing
20 min	Nothing
25 min	Gas
30 min	Gas & Water
l	Water
If bradenhead flowed water, check all of the descriptions that apply below:	
CLEAR FRESH SALTY	SULFURBLACK
5 MINUTE SHUT-IN PRESSURE BRADENHEAD 13 INTERMEDIATE NA	
BH down to nothing in 6 see through 1/4" fitting	
By Witness Witness	
(Position)	
E-mail address	