



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

RCVD APR 30 '13

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

OIL CONS. DIV.
DIST. 3

Date of Test 4-30-13 Operator COPC API #30-0 39-02400

Property Name San Juan 28-6 Well No. 59 Location: Unit N Section 14 Township 28 Range 6

Well Status (~~Shut In~~ or Producing) Initial PSI: Tubing 170 Intermediate 0.6 Casing 170 Bradenhead 183

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	5.2	0.6	165	0	170
10 min	2.2	0.6	165	0	170
15 min	0.4	0.6	167	0	170
20 min	1.0	0.6	169		
25 min	1.0	0.6	170		
30 min	0.2	0.6	169		

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow	☒	
Surges	☒	
Down to Nothing	☒	☒
Nothing		
Gas	☒	
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 5.2 INTERMEDIATE 0

REMARKS:

Bradenhead blew down in 13 min. started blowing again
at 15 min., it blows down and comes back. Intermediate
blew down to nothing in 5 sec. Requested gas Anal. and Sch.

By

Wade Hall

Witness

Paul Wicks

M30 Area 24 Run 457

(Position)

E-mail address _____