NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
http://emnrd.state.nm.us/ocd/District III/3district.htm

OIL CONS. DIV DIST. 3
MAR 22 2013

BRADENHEAD TEST REPORT
(submit 1 copy to above address)

Date of Test 3-15-13 Operator Chevron mid cont API #30-039-06921

Property Name Rincon Well No. 99 Location: Unit A Section 27 Township 27 Range 6

Well Status(Shut-In or Producing) Initial PSI: Tubing 52 Intermediate N/A Casing 109 Bradenhead 2

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing TIME	Bradenhead BH	Bradenhead Int	Bradenhead Csg	INTERM Int	INTERM Csg
5 min	0		107		
10 min	0		109		
15 min	0		107		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS

	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	X 30 sec	
Nothing		
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR____ FRESH____ SALTY____ SULFUR____ BLACK____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE N/A

REMARKS: Had Whispor for 30 sec Then dead

By Randy Calcote Witness

Calder services
(Position)

E-mail address Randy.c@calderservices.com

3-20-13