



GIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1060 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://amr.nd.state.nm.us/oc/District/103/district.htm>

OIL CONS. DIV DIST. 3

MAR 27 2013

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 3-22-13 Operator Chen mrcant API # 30-039-06922

Property Name Pike Well No. 100 Location: Unit A Section 26 Township 27 Range 6

Well Status(Shut-In or Producing) Initial PSI: Tubing 25 Intermediate X Casing 47 Bradenhead 2

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	1	47		
10 min	0		48		
15 min	0		48		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS
BRADENHEAD INTERMEDIATE

Steady Flow

Surges

Down to Nothing X

Nothing

Gas

Gas & Water

Water

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 2 INTERMEDIATE 7

REMARKS:

REMARKS: Braden Head Head Just 1-2 sec puff when opened

By Randy Calcote
Calder Services
(Position)

Witness

E-mail address Randy.c@calderservices.com

3-26-13