



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://omrmd.state.nm.us/ocd/District/District.htm>

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

APR 04 2013

Date of Test 4-2-13 Operator Chevron midcont API # 30-039-07088

Property Name Rincon Well No. 189 Location: Unit A Section 15 Township 27 Range 7

Well Status (Shut-In or Producing) Initial PSI: Tubing 111 Intermediate X Casing 129 Bradenhead 1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>128</u>		
10 min	<u>0</u>		<u>128</u>		
15 min	<u>0</u>		<u>128</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing <u>X</u>	<u>X</u>
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE X

REMARKS: Had very light Blow for 1 min then dead

By Randy calder
calder services
(Position)

Witness _____

E-mail address Randy.c@calderservices.com

4-3-13