



OK CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6778 FAX: (505) 334-6770
<http://www.nmfs.gov/aztec/>

OIL CONS. DIV DIST. 3

MAR 22 2013

(submit 1 copy to above address)

Date of Test 3-15-17 Operator C. Hewitt mrdcont API #30-039-27667

Property Name Pinson Well No. 417 Location: Unit 4 Section 27 Township 27 Range 6

Well Status (Shut-In or Producing) Initial PSI: Tubing 72 Intermediate 3 Casing 120 Bradenhead 14

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					
	Bradenhead			INTERM		
	BH	Int	Csg	Int	Csg	
TIME						
5 min	0	0	120	0	120	
10 min	0	0	120	0	120	
15 min	0	0	120	0	120	
20 min						
25 min						
30 min						

FLOW CHARACTERISTICS	
BRADENHEAD INTERMEDIATE	
Steady Flow	
Surges	
Down to Nothing	X 20sec X PUFF
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR	FRESH	SALTY	SULFUR	BLACK
-------	-------	-------	--------	-------

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 3 INTERMEDIATE 0

REMARKS:

By Randy calder
calder services
(Position)

Witness _____

E-mail address Randy.c@calderservices.com

3-20-13