



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3distric.htm](http://emnr.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-9-13 Operator Burlington Res API #30-0 45-34609
Property Name Allison 14 Well No. 41M Location: Unit 29 Section 29 Township 32 Range 6
Well Status (Shut-In or Producing) Initial PSI: Tubing 123 Intermediate 62 Casing 165 Bradenhead 1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					FLOW CHARACTERISTICS	
	BH	Bradenhead		INTERM		BRADENHEAD	INTERMEDIATE
TIME		Int	Csg	Int	Csg		
5 min	0	59	164	15	169	3 1/2 Steady Flow	
10 min	0	61	164	16	174	1 1/2 Surges	/
15 min	0	62	164	3	176	↓ Down to Nothing	/
20 min				4	177	1 1/2 Nothing	DIST. 3
25 min				4	178	1/2 Gas	OIL CONS. DIV.
30 min				3	179	1/2 Gas & Water	
						Water	RCVD MAY 9 '13

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR Int. FRESH Int. SALTY Int. SULFUR Int. BLACK Int.

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 20

REMARKS:

BH - dead at 3 DeConchs.
2nd Surging water through whole test.

By Rogers Belton
msc
(Position)

Witness Moussa Kuchling
Water analysis
schematic

E-mail address _____