



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://einnrd.state.nm.us/ocd/District III3district.htm](http://einnrd.state.nm.us/ocd/District%20III3district.htm)

RCVD JUN 3 '13

OIL CONS. DIV.

DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6/3/2013 Operator Burlington API #30-0 39-30300

Property Name San Juan 27-5 Unit Well No. 916 Location: Unit F Section 8 Township 27 Range 5

Well Status (Shut-In) or Producing Initial PSI: Tubing 81 Intermediate 16 Casing 280 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	16	290	0	560
10 min	0	16	290	0	560
15 min	0	16	290	0	560
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	X	X
Nothing		
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE TSTM

REMARKS:

Through 1" valve. Slight puff on bradenhead. Intermediate ^{blew} below down in 35 sec. Intermediate ran during MIT, pressured up to 560 psi on casing. After 5 min shut in 1 sec puff, pressure to small to measure

By Johnny L. Cole
District Supervisor
(Position)

Witness Jonell D. Kelly

E-mail address johnny.l.cole@icop.com