



NEW MEXICO ENERGY, MINERALS  
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION  
AZTEC DISTRICT OFFICE  
1000 RIO BRAZOS ROAD  
AZTEC NM 87410  
(505) 334-6178 FAX: (505) 334-6170  
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

RCVD JUN 5 '13  
OIL CONS. DIV.  
DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-JUNE-2013 Operator CONOCO API #30-039 30521  
Property Name SAN JUAN UNIT Well No. 95 Location: Unit B Section 8 Township 27 Range 4  
Well Status(Shut-In or Producing) Initial PSI: Tubing 176 Intermediate 8 Casing 161 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min		8	181		182
10 min		8	181		182
15 min		8	181		182
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	X
Nothing	X
Gas	X
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR \_\_\_\_\_ FRESH \_\_\_\_\_ SALTY \_\_\_\_\_ SULFUR \_\_\_\_\_ BLACK \_\_\_\_\_

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

OPENED BRADENHEAD AND NOTHING CAME OUT

OPENED THE INTERMEDIATE AND IT BLEW DOWN IN  
2:45 MINUTES

By Cory Schmitt

Witness [Signature]

(Position)

E-mail address \_\_\_\_\_