



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

JUN 12 2013

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-12-2013 Operator COPC API #30-0 39-23349

Property Name San Juan 287 Well No. 189E Location: Unit F Section 35 Township 28 Range 7

Well Status (Shut-In or Producing) Initial PSI: Tubing 117 Intermediate 0 Casing 135 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>	<u>0</u>	<u>138</u>	<u>—</u>	<u>140</u>
10 min	<u>0</u>	<u>0</u>	<u>138</u>	<u>—</u>	<u>140</u>
15 min	<u>0</u>	<u>0</u>	<u>139</u>	<u>—</u>	<u>141</u>
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	☒	☒
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR ☐ FRESH ☐ SALTY ☐ SULFUR ☐ BLACK ☐

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

By [Signature]
(Position) MSO

Witness Paul Wiebe

E-mail address _____