



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

JUN 12 2013

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6-12-2013 Operator CO PC API #30-0 39-26692

Property Name San Juan 28-7 Well No. 189F Location: Unit G Section 35 Township 28 Range 7

Well Status (~~Shut-In~~ or Producing) Initial PSI: Tubing 92 Intermediate 1.2 Casing 95 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead		INTERM	
		Int	Csg	Int	Csg
TIME					
5 min	0	1.2	97	0	100
10 min	0	1.2	98	0	100
15 min	0	1.2	99	0	100
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	✓
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS: Just a puff on bradenhead Intermediate blew down to
nothing in 19 sec.

By [Signature]
(Position) MSD

Witness Paul Wiehe

E-mail address _____