



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/district.htm](http://emnr.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

RCVD JUN 18 '13

OIL CONS. DIV.

DIST. 3

Date of Test 18-JUNE-2013 Operator CONOCO API #30-039-20301

Property Name SAN JUAN 27-S Well No. 121 Location: Unit 1E Section 28 Township 27 Range 5

Well Status(Shut-In or Producing) Initial PSI: Tubing 240 Intermediate 0 Casing 237 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					FLOW CHARACTERISTICS	
	Bradenhead			INTERM		BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg		
TIME							
5 min	<u>1</u>	<u>0</u>	<u>237</u>	<u>1</u>	<u>237</u>	Steady Flow	
10 min	<u>1</u>	<u>0</u>	<u>237</u>	<u>1</u>	<u>237</u>	Surges	
15 min	<u>1</u>	<u>0</u>	<u>237</u>	<u>1</u>	<u>237</u>	Down to Nothing	
20 min						Nothing	<u>X</u>
25 min						Gas	
30 min						Gas & Water	
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS:

OPENED THE BRADENHEAD AND NOTHING CAME OUT
OPENED THE INTERMEDIATE AND NOTHING CAME OUT,

By [Signature]

Witness [Signature]

(Position)

E-mail address _____