



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

JUN 12 2013

Date of Test 6-12-2013 Operator COPC API #30-0 34-20997

Property Name San Juan 28-7 Well No. 226 Location: Unit N Section 36 Township 28 Range 7

Well Status(~~Shut-In~~ or Producing) Initial PSI: Tubing 103 Intermediate 107 Casing 107 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	0	108	108	2	109
10 min	0	109	109	2	109
15 min	0	109	109	2	109
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	☒
Surges	
Down to Nothing	
Nothing	☒
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 38

REMARKS:

nothing on bradenhead. Intermediate, hard blow for
1 minute, then steady blow. 5min shut 38 PSI and climbing.

By [Signature]
(Position)

Witness Paul Wade

E-mail address _____