



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3distric.htm](http://emnrd.state.nm.us/ocd/District%20III/3distric.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

RCVD JUN 14 '13

OIL CONS. DIV.

DIST. 3

Date of Test 6-14-2013 Operator COPC API #30-0 39-20947

Property Name San Juan 28-7 Well No. 226 Location: Unit N Section 36 Township 28 Range 7

Well Status(~~Shut In~~ or Producing) Initial PSI: Tubing 108 Intermediate 106 Casing 106 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	0	106	106	0	109
10 min	0	108	108	0	109
15 min	0	109	109	0	109
20 min				0	109
25 min				0	110
30 min				0	110

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	✓
Surges	
Down to Nothing	
Nothing	✓
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 40 and going up

REMARKS:

Nothing on bradenhead. Intermediate blew hard for 45 seconds, then steady blow for 30 minutes. Rob had shut well in at the separator at start of test. Tubing 109 at 30 min.

By

MSV

(Position)

Witness

Paul Wade

Gas Analyses and well bore schematic requested

E-mail address _____