



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emnr.state.nm.us/ocd/District/III/3distric.htm>

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-2-2013 Operator COPC API #30-0 39-07227

Property Name San Juan 28-6 Well No. 93 Location: Unit M Section 36 Township 28 Range 4

Well Status (~~Shut-In~~ or Producing) Initial PSI: Tubing 165.4 Intermediate — Casing 167.9 Bradenhead 25.4

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	—	169.2		
10 min	0	—	169.7		
15 min	0	—	170.3		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	✓
Nothing	
Gas	
Gas & Water	
Water	

OIL CONS. DIV DIST. 3

JUL 02 2013

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0.3 INTERMEDIATE _____

REMARKS: Bradenhead blew down to nothing in 42 seconds

By [Signature]
MSO
(Position)

Witness Paul Wiebe

E-mail address _____