



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrnr.state.nm.us/ocd/District III/3district.htm](http://emrnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-2-2013 Operator COPC API #30-0 39-07240

Property Name San Juan 28-5 Well No. 42 Location: Unit K Section 31 Township 28 Range 5

Well Status (Shut-In or Producing) Initial PSI: Tubing 173 Intermediate 6.3 Casing 175.2 Bradenhead 1.4

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	6.3	175.8	0	176.8
10 min	0	6.3	176.2	0	176.8
15 min	0	6.3	176.7	0	177.1
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS

BRADENHEAD INTERMEDIATE

Steady Flow		
Surges		
Down to Nothing	✓	✓
Nothing		
Gas		
Gas & Water		
Water		

OIL CONS. DIV DIST. 3

JUL 02 2013

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE _____

REMARKS:

Bradenhead blew down to nothing in 14 seconds
Intermediate blew down to nothing in 14 seconds

By [Signature]
MSD
(Position)

Witness Paul Wicks

E-mail address _____