



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/district.htm](http://emnrd.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

RCVD JUL 10 '13

OIL CONS. DIV.

DIST. 3

Date of Test 7/10/2013 Operator Conoco Phillips API #30-0 39-07282

Property Name San Juan 207 Unit Well No. 94 Location: Unit N Section 30 Township 28 Range 7

Well Status (Shut-In or Producing) Initial PSI: Tubing 106 Intermediate NA Casing 110 Bradenhead 56

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead Int	Csg	Int	Csg
TIME					
5 min	0	5	112		
10 min	0		114		
15 min	0		115		
20 min	0		116		
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	X	
Nothing		
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 1.2 INTERMEDIATE NA

REMARKS:

Through 1" fittings. BH blew down in 1 min.

By Jennifer R Bidsky

(Position)

Witness Jonathan Kelly

E-mail address _____