

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Form C-141  
Revised August 8, 2011

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office to  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

Initial Report  Final Report

Name of Company <b>Burlington Resources Oil &amp; Gas Company</b>	Contact <b>Crystal Tafoya</b>
Address <b>3401 East 30<sup>th</sup> St, Farmington, NM</b>	Telephone No. <b>(505) 326-9837</b>
Facility Name: <b>San Juan 32-9 Unit 32A</b>	Facility Type: <b>Gas Well</b>

Surface Owner <b>BLM</b>	Mineral Owner <b>BLM (SF-078509)</b>	API No. <b>30-045-23298</b>
--------------------------	--------------------------------------	-----------------------------

**LOCATION OF RELEASE**

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
<b>C</b>	<b>31</b>	<b>32N</b>	<b>9W</b>	<b>790</b>	<b>North</b>	<b>800</b>	<b>West</b>	<b>San Juan</b>

Latitude 36.94623 Longitude 107.82353

**NATURE OF RELEASE**

Type of Release <b>Natural Gas / Hydrocarbon</b>	Volume of Release <b>200 mcf / 2 Gallons Condensate</b>	Volume Recovered <b>None</b>
Source of Release <b>Wellhead</b>	Date and Hour of Occurrence <b>7/1/2013 at 11:19 AM</b>	Date and Hour of Discovery <b>7/2/2013 at 10:00 AM</b>
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

**RCVD JUL 9 '13**

**OIL CONS. DIV.  
DIST. 3**

If a Watercourse was Impacted, Describe Fully.\*  
**N/A**


Describe Cause of Problem and Remedial Action Taken.\*

**1/4" nipple on plunger lubricator cracked causing 2 gallons of condensate and 200 mcf of natural gas to be released from the wellhead. The well was immediately shut-in and blew down. The cracked fitting was repaired and the affected soil was treated with Simple Green and will be monitored.**

Describe Area Affected and Cleanup Action Taken.\*

**No further remediation will be conducted on this location.**

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	<b>OIL CONSERVATION DIVISION</b>	
	Approved by Environmental Specialist: 	
Printed Name: <b>Crystal Tafoya</b>	Approval Date: <b>7/1/2013</b>	Expiration Date:
Title: <b>Field Environmental Specialist</b>	Conditions of Approval:	
E-mail Address: <b>crystal.tafoya@conocophillips.com</b>	Attached <input type="checkbox"/>	
Date: <b>7/8/2013</b> Phone: <b>(505) 326-9837</b>		

\* Attach Additional Sheets If Necessary

**WJK1319253707**