



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/district.htm](http://emnrd.state.nm.us/ocd/District%20III/district.htm)

OIL CONS. DIV DIST. 3

JUL 16 2013

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-16-2013 Operator COPC API #30-0 39-07483

Property Name San Juan 29-5 Well No. 37 Location: Unit L Section 31 Township 29 Range 5

Well Status(Shut-In or Producing) Initial PSI: Tubing 141 Intermediate 0.3 Casing 143 Bradenhead -0.4

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0	0	143	0	143
10 min	0	0	143	0	143
15 min	0	0	143	0	143
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	✓
Nothing	✓
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE 0

REMARKS: Intermediate blew down to nothing in 1 min. 10 sec.
(1/2" pipe)

By [Signature]

Witness Paul Weiss

(Position)

E-mail address _____