



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-19-13 Operator B2 America API #30-0 45-08225
Property Name GCU Well No. 134 Location: Unit M Section 17 Township 29 Range 12
Well Status (Shut-In or Producing) Initial PSI: Tubing 25 Intermediate Casing 35 Bradenhead 85

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead				
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>1.1</u>		<u>40</u>		
10 min	<u>1.1</u>		<u>44</u>		
15 min	<u>0</u>		<u>46</u>		
20 min	<u>0</u>		<u>48</u>		
25 min	<u>0</u>		<u>50</u>		
30 min	<u>0</u>		<u>50</u>		

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow	<u>1 Vapors</u>	
Surges		
Down to Nothing		
Nothing		
Gas	<u>1</u>	<u>DIST. 3</u>
Gas & Water		<u>OIL CONS. DIV.</u>
Water		<u>ROVD JUL 19 13</u>

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 1

INTERMEDIATE N/A

REMARKS:

BH Valve needs replaced - Gas Sample taken
Hard blow to med at 19 seconds. Very light at 2.5 min
10 min vapors. 15 vapors 20-25-30 had long puff when
opened after 5 min shut in
By Ray (Position) Jaloma Witness Monica Cuello

E-mail address



GCU 134
 Dakota
 API # 30-045-08225
 Meter # 52901010
 Sec. 17, T29N, R12W
 San Juan County, New Mexico

History

Spud date 7/1963

No workover history in DIMS

12/17/2008

Pulled 2 1/16" tubing and replaced with 2 3/8".

Deviation Report	
Depth	Deviation
358'	1/2 deg
851'	1/2 deg
1340'	1/2 deg
2303'	3/4 deg
2735'	1 deg
3723'	1 deg
4448'	3/4 deg
5077'	3/4 deg
5424'	3/4 deg
5706'	1/2 deg
6150'	1/2 deg

