



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emmr.state.nm.us/ocd/District I/3/district.htm](http://emmr.state.nm.us/ocd/District%20I%203/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 19-July-2013 Operator CONOCO API #30-0 39-07153
Property Name SAN JUAN 28-6 Well No. 75 Location: Unit ✓ Section 3 Township 27 Range 6
Well Status(Shut-In or Producing) Initial PSI: Tubing 118 Intermediate 147 Casing 147 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead	Csg	Int	Csg
TIME					
5 min		126	128		84
10 min		128	128		59
15 min		114	114		43
20 min		112	112		32
25 min		112	113		26
30 min		116	116		21

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	X
Surges	
Down to Nothing	
Nothing	X
Gas	X
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

RCVD JUL 19 '13

OIL CONS. DIV.
DIST. 3

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 30

REMARKS:

OPENED THE BRADEN HEAD AND NOTHING CAME OUT.
OPENED THE INTERMEDIATE AND IT BLEW DOWN FOR THE
ENTIRE 30 MINUTES. THE CASING IS SHOWING COMMUNICATION DROPPING FROM 116-21 PSI
DURING THE INTERMEDIATE TEST

By TJ Rie

Witness John Austin

(Position)

E-mail address _____