



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emr.state.nm.us/ocd/District III/3district.htm](http://emr.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 19-JULY-2013 Operator CONOCO API #30-0 39-30120
Property Name SAN JUAN 284 Well No. 2052 Location: Unit A Section 9 Township 27 Range 6
Well Status(Shut-In or Producing) Initial PSI: Tubing 95 Intermediate 02 Casing 97 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>1</u>	<u>0</u>	<u>106</u>	<u>1</u>	<u>122</u>
10 min	<u>1</u>	<u>0</u>	<u>112</u>	<u>1</u>	<u>124</u>
15 min	<u>1</u>	<u>0</u>	<u>117</u>	<u>1</u>	<u>130</u>
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	<u>X</u>
Nothing <u>✓</u>	
Gas	<u>✓</u>
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

RCVD JUL 19 '13

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

OIL CONS. DIV. _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0 DIST. 3

REMARKS:

OPENED THE BRADENHEAD AND NOTHING CAME OUT.
OPENED THE INTERMEDIATE AND IT BLEW DOWN & NOTHING
1 N 1 SECOND,

By _____

Witness _____

(Position)

E-mail address _____