



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrdd.state.nm.us/ocd/District II/3district.htm](http://emrdd.state.nm.us/ocd/District%20II/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

RCVD JUL 23 '13

OIL CONS. DIV.

DIST. 3

Date of Test 23-JULY-2013 Operator CONOCO API #30-039-29423

Property Name SAN JUAN 28-6 Well No. 115N Location: Unit 0 Section 3 Township 27 Range 6

Well Status(Shut-In or Producing) Initial PSI: Tubing 117 Intermediate 113 Casing 119 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min		1.4	120		123
10 min		1.3	121		121
15 min		1.3	121		125
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	X
Nothing	X
Gas	X
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

OPENED THE BRADENHEAD AND NOTHING CAME OUT
OPENED THE INTERMEDIATE AND IT BLEW DOWN TO
IN 10 SECONDS

By [Signature]

Witness John Durbin

(Position)

E-mail address _____