



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrds.state.nm.us/ocd/District III/3district.htm](http://emrds.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

APR 22 2013

Date of Test 4-16-13 Operator WPX Energy API #30-0 3930441

Property Name Rosa Unit Well No. 311A Location: Unit A Section 28 Township 31N Range 04W

Well Status(Shut-In or Producing) Initial PSI: Tubing 38 Intermediate N/A Casing 38 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead	INTERM			
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>	<u>N/A</u>	<u>38</u>	<u>N/A</u>	<u>38</u>
10 min	<u>0</u>	<u>N/A</u>	<u>38</u>	<u>N/A</u>	<u>38</u>
15 min	<u>0</u>	<u>N/A</u>	<u>38</u>	<u>N/A</u>	<u>38</u>
20 min					
25 min					
30 min					

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	<u>✓</u>	
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE N/A

REMARKS:

BHA shut 4-15-13. Left BHA open after Test on 4-16-13

By Jason Smith
Field Tech.
(Position)

Witness _____

E-mail address jason.smith@wpxenergy.com