



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

APR 23 2013

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 4-17-13 Operator Chevron malcon TAPI #30-0 39-06952

Property Name Rincon Well No 174 Location: Unit N Section 19 Township 22 Range 6

Well Status (Shut-In or Producing) Initial PSI: Tubing 28 Intermediate X Casing 29 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	Bradenhead			Int	Csg
	BH	Int	Csg		
TIME	very light blow		29		
5 min	very light blow		36		
10 min	very light blow		42		
15 min	very light blow		48		
20 min	very light blow		52		
25 min	very light blow		53		
30 min	very light blow				

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow <u>X very light</u>	
Surges	
Down to Nothing	
Nothing	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 INTERMEDIATE X

REMARKS:

Bradenhead Had very light Blow for all of Test

By Randy Culcote

Witness _____

Culder service
(Position)

E-mail address Randy.C@calderservice.com

4-18-13