



NEW MEXICO ENERGY, MINERALS & NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrnr.state.nm.us/ocd/District III/3distric.htm](http://emrnr.state.nm.us/ocd/District%20III/3distric.htm)

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

APR 23 2013

Date of Test 4-17-13 Operator Chewin midcott API # 30-039-27328

Property Name Rincon Well No 174P Location: Unit 3 Section 19 Township 27 Range 6

Well Status (Shut-In or Producing) Initial PSI: Tubing 52 Intermediate X Casing 52 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		52		
10 min	0		52		
15 min	0		46		
20 min					
25 min					
30 min					

all went
like
(13 min)

FLOW CHARACTERISTICS

BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing <u>X</u>	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE X

REMARKS:

Well went online at 13 min, causing csg to drop
Bradenhead was Dead all Test.

By Randy Culcote

Witness _____

Culder service

(Position)

E-mail address Randy.c@calderservice.com

4-18-13