



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/district.htm](http://emnrd.state.nm.us/ocd/District%20III/district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

RCVD AUG 9 '13
OIL CONS. DIV.
DIST. 3

Date of Test 8/9/2013 Operator Burlington API #30-0 45-32253
Property Name San Juan 32.9 unit Well No. 2825 Location: Unit P Section 33 Township 32 Range 9
Well Status (Shut-In or Producing) Initial PSI: Tubing 0 Intermediate NA Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		640		
10 min	0		640		
15 min	0		640		
20 min	0		635		
25 min	0		635		
30 min	0		635		

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing	X	
Nothing		
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE NA

REMARKS:

Ran during MIT, AWS 742 on Well for TA, slight breath for 2sec, partially opened, full opened nothing.
Casing pressured up to 640 psi, tubing closed off w/ rams

By [Signature]
ON SITE SUPERVISOR
(Position)

Witness [Signature]

E-mail address _____