



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

RCVD AUG 30 '13
OIL CONS. DIV.
DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 30-AUG-2013 Operator CONOCO/BURDIN API #30-0 4529466
Property Name MARLOTTE Well No. 2 Location: Unit 1 Section 8 Township 31 Range 10
Well Status(Shut-In or Producing) Initial PSI: Tubing 114 Intermediate 0 Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE					FLOW CHARACTERISTICS	
	Bradenhead			INTERM		BRADENHEAD	INTERMEDIATE
	BH	Int	Csg	Int	Csg		
TIME							
5 min						Steady Flow	
10 min						Surges	
15 min						Down to Nothing	
20 min						Nothing	
25 min						Gas	
30 min						Gas & Water	
						Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE 0

REMARKS:

PERFORMED BRADENHEAD TEST PRIOR TO
MIT. OPENED THE BRADENHEAD NOTHING CAME OUT
OPENED THE INTERMEDIATE AND NOTHING CAME OUT

By GENARO MAEZ

Witness [Signature]

WELL SITE SUPER

(Position)

E-mail address _____