



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-8178 FAX: (505) 334-6170
<http://emrmd.state.nm.us/ocd/District103/district.htm>

OIL CONS. DIV DIST. 3

MAY 10 2013

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 5-7-13 Operator Chevron midcont API #30-0 39-0645

Property Name Rincon Well No. 102 Location: Unit m Section 11 Township 26 Range 7

Well Status (Shut-In or Producing) Initial PSI: Tubing 74 Intermediate X Casing 75 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Bradenhead	Csg	Int	Csg
TIME					
5 min	0		75		
10 min	0		75		
15 min	0		75		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing <u>X</u>	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE X

REMARKS:

By Randy calCOTE
calder service
(Position)

Witness _____

E-mail address Randy.C@calder service.com

5-8-13