



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6173 FAX: (505) 334-6170
[http://emr.nd.state.nm.us/ocd/District 1033/district.htm](http://emr.nd.state.nm.us/ocd/District%201033/district.htm)

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

MAY 10 2013

Date of Test 5-8-13 Operator Chevron midcont API # 30-039-20774

Property Name Rincon Well No 201 Location: Unit 6 Section 02 Township 26 Range 7

Well Status (Shut-In or Producing) Initial PSI: Tubing 52 Intermediate X Casing 82 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

PRESSURE

Testing	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME	<u>Very</u>				
5 min	<u>light</u>		<u>81</u>		
10 min	<u>Very</u>		<u>81</u>		
15 min	<u>light</u>		<u>81</u>		
20 min	<u>Very</u>		<u>79</u>		
25 min	<u>light</u>		<u>80</u>		
30 min	<u>Very</u>		<u>80</u>		

FLOW CHARACTERISTICS
BRADENHEAD INTERMEDIATE

Steady Flow		
Surges		
Down to Nothing		
Nothing	<u>X</u>	
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0

INTERMEDIATE X

REMARKS:

Had very light Blow for Test,

By Randy CalcoTE

Witness

Calder Service
(Position)

E-mail address Randy.C@calderservice.com

5-9-13