



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
<http://emr.nd.state.nm.us/ocdd/District%203/district.htm>

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

JUN 07 2013

Date of Test 6-5-13 Operator Chevron midland API #30-039-06870

Property Name Riocon Well No. 76 Location: Unit H Section 34 Township 27 Range 7

Well Status (Shut-In or Producing) Initial PSI: Tubing 20 Intermediate X Casing 22 Bradenhead 1

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	0		22		
10 min	0		22		
15 min	0		22		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS
BRADENHEAD INTERMEDIATE

Steady Flow _____
Surges _____
Down to Nothing _____
Nothing X PUFF _____
Gas _____
Gas & Water _____
Water _____

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE

BRADENHEAD 0 INTERMEDIATE X

REMARKS:

By Randy CalcoTE
Calder Service
(Position)

Witness _____

E-mail address Randy.C@calder-service.com