



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

OIL CONS. DIV DIST. 3

JUN 05 2013

Date of Test 5-22-13 Operator Elm Ridge Exploration CO LLC API #30-039-21451

Property Name Candado Well No. 019 A Location: Unit D Section 3 Township 26N Range 07W

Well Status(Shut-In or Producing) Initial PSI: Tubing 132 Intermediate Casing 140 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead		INTERM	
TIME		Int	Csg	Int	Csg
5 min	<u>0</u>		<u>140</u>		
10 min	<u>0</u>		<u>140</u>		
15 min	<u>0</u>		<u>140</u>		
20 min	<u>0</u>		<u>140</u>		
25 min	<u>0</u>		<u>140</u>		
30 min	<u>0</u>		<u>140</u>		

	FLOW CHARACTERISTICS	
	BRADENHEAD	INTERMEDIATE
Steady Flow		
Surges		
Down to Nothing		
Nothing	<u>✓</u>	
Gas		
Gas & Water		
Water		

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS:

By Jason Herbig

Witness

Pumper
(Position)

E-mail address