



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnr.state.nm.us/ocd/District III/3district.htm](http://emnr.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

AUG 13 2013

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 6/27/13 Operator Elm Ridge Exploration CO LLC API #30-043-20521

Property Name Bonanza Well No. 006 Location: Unit O Section 12 Township 22N Range 03W

Well Status(Shut-In or Producing) Initial PSI: Tubing 120 Intermediate Casing 130 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	Bradenhead			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>	<u>120</u>	<u>140</u>		
10 min	<u>0</u>	<u>120</u>	<u>140</u>		
15 min	<u>0</u>	<u>120</u>	<u>140</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	<u>X</u>
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE

REMARKS:

By Lick Duan
Lampert
(Position)

Witness _____

E-mail address _____