



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emnrd.state.nm.us/ocd/District III/3district.htm](http://emnrd.state.nm.us/ocd/District%20III/3district.htm)

OIL CONS. DIV DIST. 3

AUG 06 2013

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

Date of Test 7-24-13 Operator CROSS TIMBERS ENERGY SAPI #30-0 39-30705
Property Name Breech A Well No. 136G Location: Unit Section 10G Township 26N Range 6W
Well Status (Shut-In or Producing) Initial PSI: Tubing 177 Intermediate NA Casing 193 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing TIME	PRESSURE				
	BH	Bradenhead		INTERM	
		Int	Csg	Int	Csg
5 min	<u>0</u>		<u>193</u>		
10 min	<u>0</u>		<u>193</u>		
15 min	<u>0</u>		<u>193</u>		
20 min					
25 min					
30 min					

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing <u>✓</u>	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE NA

REMARKS:

By Kevin Johnson

Witness

(Position)

E-mail address