



NEW MEXICO DEPARTMENT OF REVENUE
1000 RIO BRAZOS ROAD
ALBUQUERQUE, NEW MEXICO 87110

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-6178 FAX: (505) 334-6170
[http://emrod.state.nm.us/ocd/District III3district.htm](http://emrod.state.nm.us/ocd/District%20III3district.htm)

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

OIL CONS. DIV DIST. 3

JUN 19 2013

Date of Test MAY 23, 2013 Operator Noble Energy API #30-0 3906895

Property Name Champlin Well No. 8 Location: Unit J Section 25 Township 27N Range 4W

Well Status(Shut-In or Producing) Initial PSI: Tubing 160 Intermediate Casing 170 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE				
	BH	Bradenhead		INTERM.	
		Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>		<u>170</u>		
10 min	<u>0</u>				
15 min	<u>0</u>				
20 min	<u>0</u>				
25 min	<u>0</u>				
30 min	<u>0</u>				

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing	<u>0</u>
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD INTERMEDIATE

REMARKS:

By Brian M. King

Witness

Pumper
(Position)

E-mail address