

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Form C-141
Revised August 8, 2011

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office to
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company ConocoPhillips Company	Contact Crystal Tafoya
Address 3401 East 30th St, Farmington, NM	Telephone No. (505) 326-9837
Facility Name: San Juan 31-6 Unit 213A	Facility Type: Gas Well

Surface Owner Federal	Mineral Owner Federal (NM-03404)	API No. 30-039-27807
------------------------------	---	-----------------------------

LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
C	5	30N	6W	447	North	1880	West	Rio Arriba

Latitude 36.84756 Longitude 107.48885

NATURE OF RELEASE

Type of Release Produced Water	Volume of Release 17 bbls	Volume Recovered 16 bbls
Source of Release Transfer Pump Hose	Date and Hour of Occurrence 5/14/2013	Date and Hour of Discovery 5/15/2013 at 10:20 AM
Was Immediate Notice Given? <input type="checkbox"/> Yes <input type="checkbox"/> No <input checked="" type="checkbox"/> Not Required	If YES, To Whom?	
By Whom?	Date and Hour	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	


RCVD MAY 17 '13

If a Watercourse was Impacted, Describe Fully.* N/A	OIL CONS. DIV. DIST. 3
---	-----------------------------------

Describe Cause of Problem and Remedial Action Taken.*
On May 15, 2013 a produced water release of 17bbls was discovered from a split in a flex hose from the tank to a transfer pump. The tank valve was shut-in and a water truck dispatched to location where 16bbls of produced water was recovered. The release was contained within the berm and did not leave location.

Describe Area Affected and Cleanup Action Taken.*
ConocoPhillips will assess the soil per NMOCD Guidelines for Remediation of Leaks, Spills and Releases to determine a path forward for clean-up if necessary.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Crystal Tafoya	Approved by Environmental Specialist: 	
Title: Field Environmental Specialist	Approval Date: 9/24/2013	Expiration Date:
E-mail Address: crystal.tafoya@conocophillips.com	Conditions of Approval:	Attached <input type="checkbox"/>
Date: 5/17/2013 Phone: (505) 326-9837		

* Attach Additional Sheets If Necessary

njk1326752016