



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OIL CONSERVATION DIVISION
AZTEC DISTRICT OFFICE
1000 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 334-8178 FAX: (505) 334-6170
<http://omard.state.nm.us/ocd/District123d1strjc.htm>

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

JUN 19 2013

Date of Test 6-10-13 Operator Chevron midcont API #30-039-06780

Property Name Rincon Well No. 72 Location: Unit P Section 33 Township 27 Range 7

Well Status (Shut-In or Producing) Initial PSI: Tubing 2 Intermediate X Casing 0 Bradenhead 0

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM	
	BH	Int	Csg	Int	Csg
TIME					
5 min	<u>0</u>	<u>1</u>	<u>0</u>	<u>1</u>	<u>1</u>
10 min	<u>6</u>	<u>1</u>	<u>0</u>	<u>1</u>	<u>1</u>
15 min	<u>6</u>	<u>1</u>	<u>0</u>	<u>1</u>	<u>1</u>
20 min		<u>1</u>		<u>1</u>	<u>1</u>
25 min		<u>1</u>		<u>1</u>	<u>1</u>
30 min		<u>1</u>		<u>1</u>	<u>1</u>

FLOW CHARACTERISTICS
BRADENHEAD INTERMEDIATE

Steady Flow _____
Surges _____
Down to Nothing _____
Nothing X _____
Gas _____
Gas & Water _____
Water _____

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR _____ FRESH _____ SALTY _____ SULFUR _____ BLACK _____

5 MINUTE SHUT-IN PRESSURE BRADENHEAD 0 INTERMEDIATE X

REMARKS:

By Randy CalCOTE
Calder Service
(Position)

Witness _____

E-mail address Randy.C@calder.service.com

6-12-13