



NEW MEXICO ENERGY, MINERALS
& NATURAL RESOURCES DEPARTMENT

OLG NAT DIVISION
AZTEC DISTRICT OFFICE
1650 RIO BRAZOS ROAD
AZTEC NM 87410
(505) 234-6170 FAX: (505) 234-6170
<http://www.state.nm.us/ood/Drillbit/MSDdrillbit.htm>

OIL CONS. DIV DIST. 3

BRADENHEAD TEST REPORT

(submit 1 copy to above address)

SEP 26 2013

Date of Test 9-8-13 Operator Prody Energy Co API #30-043-20721-00

Property Name San Isidro Well No. 12-2 Location: Unit Section Township Range

Well Status (Shut-In or Producing) Initial PSI: Tubing ☒ Intermediate Casing ☒ Bradenhead ☒

OPEN BRADENHEAD AND INTERMEDIATE TO ATMOSPHERE INDIVIDUALLY FOR 15 MINUTES EACH

Testing	PRESSURE			INTERM.	
	Bradenhead			Int	Csg
	BH	Int	Csg		
TIME					
5 min	0		0		
10 min	0		0		
15 min	0		0		
20 min	0		0		
25 min	0		0		
30 min	0		0		

FLOW CHARACTERISTICS	
BRADENHEAD	INTERMEDIATE
Steady Flow	
Surges	
Down to Nothing	
Nothing ☒	
Gas	
Gas & Water	
Water	

If bradenhead flowed water, check all of the descriptions that apply below:

CLEAR FRESH SALTY SULFUR BLACK

5 MINUTE SHUT-IN PRESSURE BRADENHEAD ☒ INTERMEDIATE

REMARKS: TAD well

By [Signature]
Pumper
(Position)

Witness

E-mail address lynnh49@msn.com