

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

Initial Report Final Report

Name of Company Encana Oil and Gas (USA) Inc.	Contact Briana Gerou
Address 370 17 th Street Denver, CO 80202	Telephone No. 720-876-5830
Facility Name Lybrook A32-2306-01H	Facility Type Oil well

Surface Owner State of NM	Mineral Owner State of NM/BLM	Lease No. State: 1399 BLM: 89021
---------------------------	-------------------------------	----------------------------------

LOCATION OF RELEASE API# 30-043-21127

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
A	32	23N	6W	556	North	222	East	Sandoval

Latitude 36.18780 Longitude 107.48297

NATURE OF RELEASE

Type of Release Crude Oil	Volume of Release ~ 25 bbls	Volume Recovered Estimated 20 bbl total including contaminated soil
Source of Release Suction scrubber from VRU pressure relief	Date and Hour of Occurrence Estimated 9/8/13 at 5:00pm	Date and Hour of Discovery Estimated 9/8/13 at 5:00pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Brandon Powell	
By Whom? Briana Gerou	Date and Hour 9/9/13 3pm	ROUND SEP 23 '13
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse: N/A	OIL CONS. DIV. DIST. 3

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
Tank valves were inadvertently left closed after unloading. Pressure built up and released from the VRU suction scrubber.

Describe Area Affected and Cleanup Action Taken.*
The release that occurred on the Lybrook A 32 well site impacted the area north of the well head and surface production equipment. The bulk of the release was confined to the tank battery area within impermeable containment. A storm water collection pond, located at the north east corner of the location was impacted by isolated areas of oil sheen.
Upon discovery of release, Envirotech was dispatched to the location. Hydro excavation vacuum trucks were utilized to remove free standing oil, impacted gravel and soil, as well as the areas of impacted water in the pond. Oil absorbing booms and pads were placed in the pond to absorb any additional oil. Perimeter fencing was employed to deter wildlife entry until all oil was absorbed. Upon a one call being valid, the impacted soil was excavated and disposed of at Envirotech's Landfarm #2.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: <i>Briana Gerou</i>	OIL CONSERVATION DIVISION	
Printed Name: Briana Gerou	Approved by District Supervisor: <i>Brandon Powell</i>	
Title: Environmental Specialist	Approval Date: 10-18-2013	Expiration Date:
E-mail Address: briana.gerou@encana.com	Conditions of Approval: * Confirmation samples are required prior to final closure.	Attached <input type="checkbox"/>
Date: 9/19/13	Phone: 720 876 5830	

* Attach Additional Sheets If Necessary

28P1329148089